



http://130.149.60.45/~farbmetrik/TE96/TE96L0FP.PDF /.PS; 3D-linearization  
F: 3D-linearization TE96/TE96LE30FP.DAT in file (F), page 2/2




TE960-3, Picture B1Wdd: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (nf); ; PS operators 4 colorimage



radial gratings W-C<sub>d</sub> radial gratings W-M<sub>d</sub> radial gratings W-Y<sub>d</sub> radial gratings W-N radial gratings W-Z


TE960-5, Picture B2Wdd: radial gratings W-C<sub>d</sub>; W-M<sub>d</sub>; W-Y<sub>d</sub>; W-N; PS operator: *rgb*->*rgb<sub>dd</sub>* *setrgbcolor*




TE960-7, Picture B3Wdd: 14 CIE-test colours and 2 + 16 grey steps (sf); PS operator: *rgb/cmy0*->*rgb<sub>dd</sub>* *setrgbcolor*




test chart TE96; 2(ISO/IEC 15775 + ISO/IEC TR 24705)  
chromatic test chart CMY, 3D=1, de=0, *cmy0*\*



TE961-1, Picture B4Wdd: 16 equidistant steps W-C<sub>d</sub>; W-M<sub>d</sub>; W-Y<sub>d</sub>; W-N; *rgb/cmy0*->*rgb<sub>dd</sub>* *setrgbcolor*



TE961-3, Picture B5Wdd: Sript and Landolt-rings N; C<sub>d</sub>; M<sub>d</sub>; Y<sub>d</sub>; Z; PS operator: *rgb*->*rgb<sub>dd</sub>* *setrgbcolor*



TE961-5, Picture B6Wdd: Landolt-rings W-C<sub>d</sub>; W-M<sub>d</sub>; PS operator: *rgb*->*rgb<sub>dd</sub>* *setrgbcolor*



TE961-7, Picture B7Wdd: Landolt-rings W-Y<sub>d</sub>; W-N; PS operator: *rgb*->*rgb<sub>dd</sub>* *setrgbcolor*

input: *rgb/cmyk* -> *rgb<sub>dd</sub>*  
output: 3D-linearization to *cmy0*\*<sub>dd</sub>