

$\log \Delta L$ luminance difference threshold • $L_g = 6.3 \text{ cd/m}^2$

04 0, Is A 6,3cd/m²; pot3


$$\Delta L = [A_1 + A_3 \cdot L]^t$$

$$A_1 = 0.11$$

$$A_2 = 1.28 = t$$

$$A_3 = 0.06$$

$$\Delta = 0.004$$



$\log(L/\Delta L)$ luminance contrast sensitivity threshold • $L_g = 6.3 \text{ cd/m}^2$

04 0, Is A 6,3cd/m²; pot3


$$\log(L/\Delta L) = L / [A_1 + A_3 \cdot L]^t$$

$$A_1 = 0.11$$

$$A_2 = 1.28 = t$$

$$A_3 = 0.06$$

$$\Delta = 0.004$$



$L/\Delta L$ luminance contrast
sensitivity threshold

• $L_g = 6.3 \text{ cd/m}^2$

04 0, Is A 6,3cd/m²; pot3


$$L/\Delta L = L / [A_1 + A_3 \cdot L]^t$$

$$A_1 = 0.11$$

$$A_2 = 1.28 = t$$

$$A_3 = 0.06$$

$$\Delta = 0.004$$



T^* luminance difference threshold sum

• $I_g = 6.3 \text{ cd/m}^2$

80 T 04 0, Is A 6,3cd/m²; pot3

$$T^* = [A_1 + A \cdot L]^t - 1$$

$$A_1 = 0.11$$

$$A_2 = 1.28 = t$$

$$A_3 = 0.06$$

$$\Delta = 0.004$$

