

95.18	100.0	44.15	188.03	196.9	86.68	189.17	198.1	87.21	1.0	0.29	0.29	0.29	0.14	0.13	1.54	21000.3 (WPN_WN60)	129 0 0	
$\Delta(L^*,a^*,b^*):0,29\ 0,00\ 0,00$					$(L^*0,a^*0,b^*0):129,39\ 0,67\ 0,25$					$(L^*1,a^*1,b^*1):129,68\ 0,67\ 0,25$					$(L^*m,a^*m,b^*m):129,54\ 0,67\ 0,25$			
95.18	100.0	44.15	70.17	74.13	34.75	70.56	74.54	34.94	1.0	0.19	0.19	0.19	0.1	0.12	1.37	21000.3 (WPN_WN60)	89 0 -3	
$\Delta(L^*,a^*,b^*):0,19\ 0,00\ 0,00$					$(L^*0,a^*0,b^*0):88,99\ 0, -3,$					$(L^*1,a^*1,b^*1):89,18\ 0, -3,$					$(L^*m,a^*m,b^*m):89,08\ 0, -3,$			
95.18	100.0	44.15	32.53	34.31	16.02	32.7	34.49	16.11	1.0	0.14	0.14	0.14	0.09	0.11	1.24	21000.3 (WPN_WN60)	65 0 -2	
$\Delta(L^*,a^*,b^*):0,14\ 0,00\ 0,00$					$(L^*0,a^*0,b^*0):65,21\ 0, -2,$					$(L^*1,a^*1,b^*1):65,35\ 0, -2,$					$(L^*m,a^*m,b^*m):65,28\ 0, -2,$			
95.18	100.0	44.15	16.92	17.69	7.98	17.01	17.78	8.02	1.0	0.12	0.12	0.12	0.09	0.12	1.25	21000.3 (WPN_WN60)	49 0 0	
$\Delta(L^*,a^*,b^*):0,12\ 0,00\ 0,00$					$(L^*0,a^*0,b^*0):49,13\ 0,46\ 0,$					$(L^*1,a^*1,b^*1):49,25\ 0,46\ 0,$					$(L^*m,a^*m,b^*m):49,19\ 0,46\ 0,$			
95.18	100.0	44.15	8.86	9.15	3.85	8.93	9.23	3.88	1.0	0.15	0.15	0.15	0.14	0.12	1.7	21000.3 (WPN_WN60)	36 1 1	
$\Delta(L^*,a^*,b^*):0,15\ 0, 0,$					$(L^*0,a^*0,b^*0):36,29\ 1,28\ 1,41$					$(L^*1,a^*1,b^*1):36,44\ 1,26\ 1,40$					$(L^*m,a^*m,b^*m):36,36\ 1,27\ 1,40$			
95.18	100.0	44.15	4.58	4.65	1.77	4.62	4.7	1.8	1.0	0.15	0.15	0.15	0.18	0.11	1.7	21000.3 (WPN_WN60)	25 1 3	
$\Delta(L^*,a^*,b^*):0,15\ 0, 0,$					$(L^*0,a^*0,b^*0):25,75\ 2,00\ 3,38$					$(L^*1,a^*1,b^*1):25,90\ 1,98\ 3,35$					$(L^*m,a^*m,b^*m):25,83\ 1,99\ 3,36$			
95.18	100.0	44.15	2.95	3.14	1.54	2.99	3.19	1.57	1.0	0.19	0.19	0.19	0.28	0.13	2.12	21000.3 (WPN_WN60)	20 0 -2	
$\Delta(L^*,a^*,b^*):0,19\ 0,00\ 0,02$					$(L^*0,a^*0,b^*0):20,65\ 0, -2,$					$(L^*1,a^*1,b^*1):20,84\ 0, -2,$					$(L^*m,a^*m,b^*m):20,75\ 0, -2,$			
90.38	100.0	87.54	4.52	14.96	18.28	4.59	15.03	18.34	1.0	0.47	0.47	0.13	0.16	0.13	1.1	11000.3 (GDR_WN60)	45 -80 -12	
$\Delta(L^*,a^*,b^*):0,09\ 0,46\ 0,03$					$(L^*0,a^*0,b^*0):45,59 -81, -12,$					$(L^*1,a^*1,b^*1):45,69 -80, -12,$					$(L^*m,a^*m,b^*m):45,64 -80, -12,$			
90.38	100.0	87.54	10.21	15.71	16.22	10.27	15.78	16.28	1.0	0.14	0.14	0.1	0.09	0.1	0.99	11000.3 (GDR_WN60)	46 -28 -6	
$\Delta(L^*,a^*,b^*):0,09\ 0,11\ 0,01$					$(L^*0,a^*0,b^*0):46,61 -28, -6,$					$(L^*1,a^*1,b^*1):46,70 -27, -6,$					$(L^*m,a^*m,b^*m):46,65 -28, -6,$			
90.38	100.0	87.54	14.83	16.52	14.83	14.89	16.59	14.89	1.0	0.08	0.08	0.08	0.07	0.08	0.92	11000.3 (GDR_WN60)	47 0 0	
$\Delta(L^*,a^*,b^*):0,08\ 0,00\ 0,00$					$(L^*0,a^*0,b^*0):47,66\ 0, 0,$					$(L^*1,a^*1,b^*1):47,75\ 0, 0,$					$(L^*m,a^*m,b^*m):47,71\ 0, 0,$			
90.38	100.0	87.54	32.65	16.96	21.4	32.72	17.04	21.47	1.0	0.2	0.2	0.1	0.09	0.1	1.17	11000.3 (GDR_WN60)	48 79 -14	
$\Delta(L^*,a^*,b^*):0,10\ 0, 0,04$					$(L^*0,a^*0,b^*0):48,22\ 79,32 -14,$					$(L^*1,a^*1,b^*1):48,32\ 79,15 -14,$					$(L^*m,a^*m,b^*m):48,27\ 79,24 -14,$			
90.38	100.0	87.54	39.3	17.17	24.55	39.37	17.26	24.62	1.0	0.28	0.28	0.12	0.11	0.12	1.37	11000.3 (GDR_WN60)	48 100 -19	
$\Delta(L^*,a^*,b^*):0,11\ 0, 0,06$					$(L^*0,a^*0,b^*0):48,49\ 100,85 -19,$					$(L^*1,a^*1,b^*1):48,60\ 100,60 -19,$					$(L^*m,a^*m,b^*m):48,54\ 100,73 -19,$			
90.38	100.0	87.54	14.82	17.29	27.23	14.88	17.36	27.3	1.0	0.09	0.09	0.08	0.07	0.08	0.94	11000.3 (BDY_WN60)	48 -4 -24	
$\Delta(L^*,a^*,b^*):0,08\ 0,00\ 0,03$					$(L^*0,a^*0,b^*0):48,64 -4, -24,$					$(L^*1,a^*1,b^*1):48,72 -4, -24,$					$(L^*m,a^*m,b^*m):48,68 -4, -24,$			
90.38	100.0	87.54	15.24	17.26	20.47	15.3	17.32	20.53	1.0	0.07	0.07	0.07	0.06	0.07	0.77	11000.3 (BDY_WN60)	48 -2 -11	
$\Delta(L^*,a^*,b^*):0,07\ 0,00\ 0,01$					$(L^*0,a^*0,b^*0):48,59 -2, -11,$					$(L^*1,a^*1,b^*1):48,67 -2, -11,$					$(L^*m,a^*m,b^*m):48,63 -2, -11,$			
90.38	100.0	87.54	14.79	16.44	14.52	14.84	16.51	14.58	1.0	0.07	0.07	0.07	0.06	0.07	0.79	11000.3 (BDY_WN60)	47 0 0	
$\Delta(L^*,a^*,b^*):0,07\ 0,00\ 0,00$					$(L^*0,a^*0,b^*0):47,57\ 0, 0,$					$(L^*1,a^*1,b^*1):47,64\ 0, 0,$					$(L^*m,a^*m,b^*m):47,61\ 0, 0,$			
90.38	100.0	87.54	16.97	17.72	4.43	17.02	17.78	4.48	1.0	0.18	0.18	0.09	0.09	0.09	0.8	11000.3 (BDY_WN60)	49 5 38	
$\Delta(L^*,a^*,b^*):0,07\ 0, 0,$					$(L^*0,a^*0,b^*0):49,16\ 5,49\ 38,33$					$(L^*1,a^*1,b^*1):49,24\ 5,47\ 38,15$					$(L^*m,a^*m,b^*m):49,20\ 5,48\ 38,24$			
90.38	100.0	87.54	17.98	18.46	0.7	18.04	18.52	0.75	1.0	0.79	0.79	0.19	0.27	0.2	0.79	11000.3 (BDY_WN60)	50 7 73	
$\Delta(L^*,a^*,b^*):0,07\ 0, 0,$					$(L^*0,a^*0,b^*0):50,06\ 7,23\ 73,73$					$(L^*1,a^*1,b^*1):50,13\ 7,21\ 72,93$					$(L^*m,a^*m,b^*m):50,09\ 7,22\ 73,33$			

95.18	100.0	44.15	189.09	197.47	86.99	188.12	197.52	86.9	1.13	1.13	1.08	1.59	1.63	1.31	21000.2 (WPN_RG60) 129 0 0				
$\Delta(L^*,a^*,b^*):0,01-1,0,10$					$(L^*0,a^*0,b^*0):129,53,1,24,0,20$					$(L^*1,a^*1,b^*1):129,54,0,11,0,31$					$(L^*m,a^*m,b^*m):129,54,0,67,0,25$				
95.18	100.0	44.15	70.57	74.32	34.87	70.17	74.35	34.82	1.0	0.9	0.9	0.85	1.18	1.24	1.4	21000.2 (WPN_RG60) 89 0 -3			
$\Delta(L^*,a^*,b^*):0,00,0,0,10$					$(L^*0,a^*0,b^*0):89,08,0,-3,$					$(L^*1,a^*1,b^*1):89,09-1,-3,$					$(L^*m,a^*m,b^*m):89,08,0,-3,$				
95.18	100.0	44.15	32.72	34.39	16.08	32.52	34.4	16.05	1.0	0.75	0.75	0.72	1.0	1.07	1.46	21000.2 (WPN_RG60) 65 0 -2			
$\Delta(L^*,a^*,b^*):0,00,0,0,08$					$(L^*0,a^*0,b^*0):65,28,0,-2,$					$(L^*1,a^*1,b^*1):65,29,0,-2,$					$(L^*m,a^*m,b^*m):65,28,0,-2,$				
95.18	100.0	44.15	17.03	17.73	8.0	16.91	17.74	8.0	1.0	0.72	0.72	0.7	1.02	1.04	1.62	21000.2 (WPN_RG60) 49 0 0			
$\Delta(L^*,a^*,b^*):0,01,0,0,06$					$(L^*0,a^*0,b^*0):49,18,0,82,0,$					$(L^*1,a^*1,b^*1):49,19,0,11,0,$					$(L^*m,a^*m,b^*m):49,19,0,46,0,$				
95.18	100.0	44.15	8.93	9.19	3.87	8.86	9.19	3.86	1.0	0.62	0.62	0.59	0.85	0.87	1.55	21000.3 (WPN_RG60) 36 1 1			
$\Delta(L^*,a^*,b^*):0,00,0,0,07$					$(L^*0,a^*0,b^*0):36,36,1,58,1,37$					$(L^*1,a^*1,b^*1):36,36,0,96,1,44$					$(L^*m,a^*m,b^*m):36,36,1,27,1,40$				
95.18	100.0	44.15	4.62	4.68	1.79	4.58	4.68	1.78	1.0	0.65	0.65	0.6	0.9	0.89	1.63	21000.3 (WPN_RG60) 25 1 3			
$\Delta(L^*,a^*,b^*):0,00,0,0,07$					$(L^*0,a^*0,b^*0):25,83,2,31,3,34$					$(L^*1,a^*1,b^*1):25,83,1,66,3,41$					$(L^*m,a^*m,b^*m):25,83,1,99,3,37$				
95.18	100.0	44.15	2.99	3.17	1.56	2.95	3.17	1.55	1.0	0.67	0.67	0.65	0.9	0.94	1.6	21000.3 (WPN_RG60) 20 0 -2			
$\Delta(L^*,a^*,b^*):0,00,0,0,06$					$(L^*0,a^*0,b^*0):20,75,0,-2,$					$(L^*1,a^*1,b^*1):20,75-1,-2,$					$(L^*m,a^*m,b^*m):20,75,0,-2,$				
90.38	100.0	87.54	4.69	14.99	18.32	4.42	15.0	18.31	1.0	3.6	3.6	0.81	1.16	0.8	2.28	11000.2 (GDR_RG60) 45 -80 -12			
$\Delta(L^*,a^*,b^*):0,01-3,0,04$					$(L^*0,a^*0,b^*0):45,64-79,-12,$					$(L^*1,a^*1,b^*1):45,65-82,-12,$					$(L^*m,a^*m,b^*m):45,64-80,-12,$				
90.38	100.0	87.54	10.34	15.74	16.25	10.14	15.75	16.24	1.0	1.69	1.69	0.78	0.89	0.79	2.34	11000.2 (GDR_RG60) 46 -28 -6			
$\Delta(L^*,a^*,b^*):0,01-1,0,05$					$(L^*0,a^*0,b^*0):46,65-27,-6,$					$(L^*1,a^*1,b^*1):46,66-28,-6,$					$(L^*m,a^*m,b^*m):46,65-28,-6,$				
90.38	100.0	87.54	14.92	16.55	14.86	14.8	16.56	14.85	1.0	0.79	0.79	0.77	1.14	1.13	1.71	11000.2 (GDR_RG60) 47 0 0			
$\Delta(L^*,a^*,b^*):0,01,0,0,02$					$(L^*0,a^*0,b^*0):47,70,0,0,$					$(L^*1,a^*1,b^*1):47,71-1,0,$					$(L^*m,a^*m,b^*m):47,71,0,0,$				
90.38	100.0	87.54	32.83	16.99	21.44	32.54	17.0	21.43	1.0	1.09	1.09	0.24	0.37	0.24	1.76	11000.2 (GDR_RG60) 48 79 -14			
$\Delta(L^*,a^*,b^*):0,01-1,0,03$					$(L^*0,a^*0,b^*0):48,26,79,79-14,$					$(L^*1,a^*1,b^*1):48,27,78,69-14,$					$(L^*m,a^*m,b^*m):48,27,79,24-14,$				
90.38	100.0	87.54	39.49	17.21	24.58	39.18	17.23	24.58	1.0	1.1	1.1	0.2	0.34	0.2	1.63	11000.2 (GDR_RG60) 48 100 -19			
$\Delta(L^*,a^*,b^*):0,02-1,0,03$					$(L^*0,a^*0,b^*0):48,53,101,28-19,$					$(L^*1,a^*1,b^*1):48,56,100,17-19,$					$(L^*m,a^*m,b^*m):48,54,100,72-19,$				
90.38	100.0	87.54	14.92	17.32	27.26	14.77	17.33	27.27	1.0	0.94	0.94	0.68	0.8	0.75	1.87	11000.2 (BDY_RG60) 48 -4 -24			
$\Delta(L^*,a^*,b^*):0,01,0,0,01$					$(L^*0,a^*0,b^*0):48,67-4,-24,$					$(L^*1,a^*1,b^*1):48,69-5,-24,$					$(L^*m,a^*m,b^*m):48,68-4,-24,$				
90.38	100.0	87.54	15.33	17.28	20.5	15.21	17.29	20.5	1.0	0.79	0.79	0.67	0.94	0.94	1.66	11000.2 (BDY_RG60) 48 -2 -11			
$\Delta(L^*,a^*,b^*):0,01,0,0,02$					$(L^*0,a^*0,b^*0):48,62-1,-11,$					$(L^*1,a^*1,b^*1):48,64-2,-11,$					$(L^*m,a^*m,b^*m):48,63-2,-11,$				
90.38	100.0	87.54	14.87	16.48	14.56	14.76	16.48	14.54	1.0	0.7	0.7	0.69	1.06	1.02	1.52	11000.2 (BDY_RG60) 47 0 0			
$\Delta(L^*,a^*,b^*):0,00,0,0,03$					$(L^*0,a^*0,b^*0):47,61,0,0,$					$(L^*1,a^*1,b^*1):47,61,0,0,$					$(L^*m,a^*m,b^*m):47,61,0,0,$				
90.38	100.0	87.54	17.07	17.74	4.46	16.92	17.75	4.44	1.0	0.86	0.86	0.55	0.78	0.65	1.82	11000.2 (BDY_RG60) 49 5 38			
$\Delta(L^*,a^*,b^*):0,01,0,0,11$					$(L^*0,a^*0,b^*0):49,19,5,91,38,18$					$(L^*1,a^*1,b^*1):49,20,5,05,38,30$					$(L^*m,a^*m,b^*m):49,20,5,48,38,24$				
90.38	100.0	87.54	18.09	18.48	0.74	17.93	18.49	0.72	1.0	1.01	1.01	0.46	0.64	0.59	1.95	11000.2 (BDY_RG60) 50 7 73			
$\Delta(L^*,a^*,b^*):0,01,0,0,40$					$(L^*0,a^*0,b^*0):50,09,7,69,73,12$					$(L^*1,a^*1,b^*1):50,10,6,76,73,53$					$(L^*m,a^*m,b^*m):50,09,7,22,73,33$				

95.18	100.0	44.15	188.65	197.48	86.02	188.56	197.52	87.10	1.76	1.76	1.72	2.49	1.72	1.7	21000.1 (WPN_BY60)	129 0 0
$\Delta(L^*,a^*,b^*):0,00,0,-1,$						$(L^*0,a^*0,b^*0):129,53,0,74$	1,13		$(L^*1,a^*1,b^*1):129,54,0,60$	0,				$(L^*m,a^*m,b^*m):129,54,0,67$	0,25	
95.18	100.0	44.15	70.38	74.32	34.52	70.35	74.35	35.18	1.16	1.16	1.02	1.4	1.0	1.57	21000.1 (WPN_BY60)	89 0 -3
$\Delta(L^*,a^*,b^*):0,00,0,-1,$						$(L^*0,a^*0,b^*0):89,08,0,-3,$			$(L^*1,a^*1,b^*1):89,09,0,-4,$					$(L^*m,a^*m,b^*m):89,08,0,-3,$		
95.18	100.0	44.15	32.62	34.39	15.89	32.61	34.4	16.24	1.02	1.02	0.93	1.32	0.91	1.71	21000.1 (WPN_BY60)	65 0 -2
$\Delta(L^*,a^*,b^*):0,00,0,-1,$						$(L^*0,a^*0,b^*0):65,28,0,-2,$			$(L^*1,a^*1,b^*1):65,29,0,-3,$					$(L^*m,a^*m,b^*m):65,28,0,-2,$		
95.18	100.0	44.15	16.97	17.74	7.9	16.96	17.74	8.1	0.95	0.95	0.93	1.41	0.93	1.81	21000.1 (WPN_BY60)	49 0 0
$\Delta(L^*,a^*,b^*):0,00,0,0,$						$(L^*0,a^*0,b^*0):49,19,0,51$	0,		$(L^*1,a^*1,b^*1):49,19,0,42$	-1,				$(L^*m,a^*m,b^*m):49,19,0,46$	0,	
95.18	100.0	44.15	8.9	9.19	3.8	8.89	9.19	3.94	1.08	1.08	1.0	1.43	1.02	2.17	21000.1 (WPN_BY60)	36 1 1
$\Delta(L^*,a^*,b^*):0,00,0,-1,$						$(L^*0,a^*0,b^*0):36,36,1,32$	1,95		$(L^*1,a^*1,b^*1):36,36,1,23$	0,86				$(L^*m,a^*m,b^*m):36,36,1,27$	1,41	
95.18	100.0	44.15	4.6	4.68	1.73	4.6	4.68	1.84	1.31	1.31	1.12	1.54	1.15	2.47	21000.1 (WPN_BY60)	25 1 3
$\Delta(L^*,a^*,b^*):0,00,0,-1,$						$(L^*0,a^*0,b^*0):25,83,2,03$	4,03		$(L^*1,a^*1,b^*1):25,83,1,93$	2,72				$(L^*m,a^*m,b^*m):25,83,1,98$	3,37	
95.18	100.0	44.15	2.97	3.17	1.52	2.97	3.17	1.59	0.97	0.97	0.89	1.28	0.88	2.08	21000.1 (WPN_BY60)	20 0 -2
$\Delta(L^*,a^*,b^*):0,00,0,0,$						$(L^*0,a^*0,b^*0):20,75,0,-1,$			$(L^*1,a^*1,b^*1):20,75,0,-2,$					$(L^*m,a^*m,b^*m):20,75,0,-2,$		
90.38	100.0	87.54	4.57	15.0	18.19	4.55	15.0	18.43	0.57	0.57	0.22	0.22	0.22	2.17	11000.0 (GDR_BY60)	45 -80 -12
$\Delta(L^*,a^*,b^*):0,00,0,0,$						$(L^*0,a^*0,b^*0):45,64,-80,-12,$			$(L^*1,a^*1,b^*1):45,64,-80,-12,$					$(L^*m,a^*m,b^*m):45,64,-80,-12,$		
90.38	100.0	87.54	10.25	15.75	16.15	10.23	15.75	16.35	0.47	0.47	0.31	0.3	0.3	1.84	11000.0 (GDR_BY60)	46 -28 -6
$\Delta(L^*,a^*,b^*):0,00,0,0,$						$(L^*0,a^*0,b^*0):46,65,-27,-5,$			$(L^*1,a^*1,b^*1):46,65,-28,-6,$					$(L^*m,a^*m,b^*m):46,65,-28,-6,$		
90.38	100.0	87.54	14.86	16.56	14.76	14.85	16.56	14.96	0.49	0.49	0.48	0.71	0.48	1.87	11000.0 (GDR_BY60)	47 0 0
$\Delta(L^*,a^*,b^*):0,00,0,0,$						$(L^*0,a^*0,b^*0):47,71,0,0,$			$(L^*1,a^*1,b^*1):47,71,0,-1,$					$(L^*m,a^*m,b^*m):47,71,0,0,$		
90.38	100.0	87.54	32.69	16.99	21.27	32.68	17.0	21.6	0.63	0.63	0.28	0.54	0.23	2.62	11000.0 (GDR_BY60)	48 79 -14
$\Delta(L^*,a^*,b^*):0,01,0,0,$						$(L^*0,a^*0,b^*0):48,26,79,28$	-14,00		$(L^*1,a^*1,b^*1):48,27,79,20$	-14,				$(L^*m,a^*m,b^*m):48,27,79,24$	-14,	
90.38	100.0	87.54	39.34	17.21	24.37	39.33	17.22	24.8	0.74	0.74	0.29	0.57	0.23	3.12	11000.0 (GDR_BY60)	48 100 -19
$\Delta(L^*,a^*,b^*):0,01,0,0,$						$(L^*0,a^*0,b^*0):48,54,100,77$	-19,		$(L^*1,a^*1,b^*1):48,55,100,68$	-20,				$(L^*m,a^*m,b^*m):48,54,100,73$	-19,	
90.38	100.0	87.54	14.85	17.33	27.16	14.84	17.33	27.37	0.37	0.37	0.17	0.2	0.17	1.55	11000.0 (BDY_BY60)	48 -4 -24
$\Delta(L^*,a^*,b^*):0,00,0,0,$						$(L^*0,a^*0,b^*0):48,68,-4,-23,$			$(L^*1,a^*1,b^*1):48,68,-4,-24,$					$(L^*m,a^*m,b^*m):48,68,-4,-24,$		
90.38	100.0	87.54	15.28	17.29	20.39	15.26	17.29	20.61	0.44	0.44	0.28	0.34	0.29	1.75	11000.0 (BDY_BY60)	48 -2 -11
$\Delta(L^*,a^*,b^*):0,00,0,0,$						$(L^*0,a^*0,b^*0):48,63,-2,-11,$			$(L^*1,a^*1,b^*1):48,63,-2,-12,$					$(L^*m,a^*m,b^*m):48,63,-2,-11,$		
90.38	100.0	87.54	14.82	16.48	14.46	14.81	16.48	14.64	0.46	0.46	0.45	0.7	0.46	1.74	11000.0 (BDY_BY60)	47 0 0
$\Delta(L^*,a^*,b^*):0,00,0,0,$						$(L^*0,a^*0,b^*0):47,61,0,0,$			$(L^*1,a^*1,b^*1):47,61,0,0,$					$(L^*m,a^*m,b^*m):47,61,0,0,$		
90.38	100.0	87.54	17.0	17.75	4.34	16.99	17.75	4.57	1.24	1.24	0.45	0.54	0.45	1.6	11000.0 (BDY_BY60)	49 5 38
$\Delta(L^*,a^*,b^*):0,00,0,-1,$						$(L^*0,a^*0,b^*0):49,20,5,52$	38,86		$(L^*1,a^*1,b^*1):49,20,5,43$	37,62				$(L^*m,a^*m,b^*m):49,20,5,48$	38,24	
90.38	100.0	87.54	18.02	18.48	0.59	18.01	18.49	0.86	4.85	4.85	1.1	1.59	1.14	1.74	11000.0 (BDY_BY60)	50 7 73
$\Delta(L^*,a^*,b^*):0,01,0,-4,$						$(L^*0,a^*0,b^*0):50,09,7,28$	75,70		$(L^*1,a^*1,b^*1):50,10,7,16$	70,85				$(L^*m,a^*m,b^*m):50,09,7,22$	73,28	