






Picture C1: Radial gratings (Siemens-stars) N-W, W-N, N-Z and W-Z; Use of the PS operator  $w^*$  setgray




Picture C2: 5 visual equidistant  $L^*$ -grey steps +  $N_0$  +  $W_1$ ; Use of the PS operator  $w^*$  setgray




Picture C3: 16 visual equidistant  $L^*$ -grey steps; Use of the PS operator  $w^*$  setgray


Fig. C1 to C6 of ISO/IEC-test chart 3; ISO/IEC 15775 and input:  $w^*$  setgray  
DIS ISO/IEC 19839-X; output:  $w^*$  setgray



Picture C4: Landolt-rings W-N; Use of the PS operator  $w^*$  setgray



Picture C5: Line raster under 45° (or 135°); Use of the PS operator  $w^*$  setgray



Picture C6: Line raster under 90° (or 0°); Use of the PS operator  $w^*$  setgray